Weekly Report Report # 23

June 27, 2020

Norway House Cree Nation

Health Centre of Excellence



Project:

- CD3 – Professional Accommodations

Larry Cove



Project Name: Professional		Project Number: CD3 – 19015B	
Accommodations			
	S	afety Statistics	
Description	Previously Reported	This Period	Project to Date
Man Hours	32490.25	858.50	33348.75
Sub trades	1144	156	1300
FLHAs	4132	137	4269
First Aides	14	0	14
Incidents	9	0	9
Daily Covid-19	823	99	922
Screenings			
	Qua	ality/Engineering	
Items	Submitted	Resolved	Outstanding
RFIs	45	44	1
Shop Drawings	59	53	6
NCRs	1	0	1

Outstanding Concerns:

o RFIs

o RFI 040 Exterior Entrance Slabs – June 18/20

Shop Drawings

- o SD 041 Resilient Flooring June 4/20
- o SD 023 Rev 01 Electrical Lighting June 5/20
- o SD 044 Hollow Metal Doors Frames and Hardware June 9/20
- o SD 046 Water Closets WC-1 and WC-2 June 15/20
- o SD 050 Gypsum Concrete Underlayment June 23/20
- o SD 051 Roofing June 26/20

o NCR's

o NCR 01 – Elevator Shaft Wall Concrete Segregation – May 20/20



Completed This Period	Comments or Concerns	
Roof Truss Install		
Roof Sheathing Install		
Fascia Board Install		
Prepare Mock-ups for Suite A1;		
A3A and A2		
Mechanical Rough Ins		
To Complete Next Period	To complete the following Period	
	Continue roof framing	
Install roof sheathing	Continue roof sheathing	
Install fascia boards	Continue fascia board install	
Install roof bracing	Continue Roof Bracing	
Mechanical rough ins	Continue Mechanical rough ins	
Electrical rough ins	Continue Electrical rough ins	
	Roofing (shingles)	
	Dampproof and install cement board panels on exterior of grade beam and backfill	
	Blocking wood walls	



Progress Photos



Exterior View – South East Side



Exterior View – South West End



Fascia Board Install – West Wing



Fascia Board Install – North West Wing



Progress Photos



Roof Sheathing Install – West End



Roof Sheathing Clip Install – West Wing



Roof Truss Install – East End



Gable End Truss Install – West Wing



Progress Photos



Plumbing Lines Install – Ceiling Laundry Room



Plumbing Lines Install to Second Floor



Duct Work Install in Crawlspace – East Wing



Duct Work Install at Stair No 2-West End