

Weekly Progress Report

Jul 10, 2020

REPORT DETAILS

Description Weekly Progress Report # 1 Submitted by Aman Chana

Status Submitted


Last update Jul 10, 2020 3:59 PM

Last updated by Aman Chana

1. WORK LOG

| Crew | # Workers | # Total hours | Work performed |
|--------|-----------|---------------|-----------------------|
| JNR | 13 | 936 | See below for details |
| Totals | 13 | 936 | |

| 2. CREW ONSITE | | | | |
|-----------------------------------------------------------|--|--|--|--|
| 2.1 The following crews were active in this report period | | | | |
| JNR | | | | |
| Mechanical | | | | |
| Electrical | | | | |





4. STRUCTURAL

4.1 Ongoing Work

Drilling for Concrete foundation dowels
 Structural Layout of footing locations

4.2 Completed Work

N/A

5. MECHANICAL 5.1 Ongoing Work N/A 5.2 Completed Work N/A

| 6. E | ELECTRICAL | |
|------|------------------|--|
| 6.1 | Ongoing Work N/A | |
| 6.2 | Completed Work | |

7. CIVIL

7.1 Ongoing Work

Blasting and Excavation Site Preparation

- 1. Drilling and placing blasting charges
- 2. Excavation of blasted materials
- 3. Excavation for sump pit locations and weeping tile
- 4. Dewatering excavated areas
- 5. Site access road preparation
- 7.2 Completed Work

N/A

NOTES

Site Supervisor Wayne Dee mobilized to site April 28th 2020 Site Supervisor David Somerville mobilized to site June 12th 2020

Work being completed on site to date:

- 1.Ongoing preparation and setup of site trailers.
- 2. Framing and dry walling interior partitions of site trailers.
- 3. Framing of exterior wood decks and pathways in between trailers
- 4. Setup of temporary site electrical generators
- 5. Setup of site sanitation facilities
- 6. Blasting days lost due to inclement weather i.e. rain and lightning; 14 days

Blasting materials can not be out in the threat of thunderstorms due to explosive materials safety protocols

PHOTOS (23)



Preparation for dewatering due to heavy rainfall **Wayne Dee** Jul 10, 2020 2:16 PM



Drilling for pad locations Wayne Dee Jul 10, 2020 2:16 PM





Preparation for dewatering due to heavy rainfall Wayne Dee Jul 10, 2020 2:15 PM



Excavation post blasting Hooman Kazempour Jul 10, 2020 1:02 PM



Deck framing in progress **Hooman Kazempour** Jul 10, 2020 1:02 PM



Deck framing in progress Hooman Kazempour Jul 10, 2020 1:02 PM

19015D-NHCN-Health Centre





Drone shot of site office setup David Somerville Jul 7, 2020 5:29 PM



Site access road preparations **David Somerville** Jul 7, 2020 5:29 PM



Site access road preparations **David Somerville** Jul 7, 2020 5:29 PM



Drone shot of site trailer setup David Somerville Jul 7, 2020 5:29 PM





Site access road preparations David Somerville Jul 7, 2020 5:29 PM



Drone shot of site David Somerville Jul 7, 2020 5:29 PM



Excavation post blasting **David Somerville** Jul 7, 2020 5:29 PM



Drone shot of excavated areas David Somerville Jul 7, 2020 5:29 PM

19015D-NHCN-Health Centre





Drone shot of site office setup David Somerville Jul 7, 2020 5:29 PM



Drilling for blast charges David Somerville Jul 7, 2020 5:29 PM



Dewatering operations **David Somerville** Jul 7, 2020 5:29 PM



Drilling for blast charges David Somerville Jul 7, 2020 5:29 PM





Site trailer deck framing David Somerville Jul 7, 2020 5:29 PM



Excavation post blasting David Somerville Jul 7, 2020 5:29 PM



Temp mechanical/electrical at trailers David Somerville Jul 7, 2020 5:29 PM



Site trailer interior finishing **David Somerville** Jul 7, 2020 5:29 PM

19015D-NHCN-Health Centre

Norway House, Manitoba





Site trailer deck framing David Somerville Jul 7, 2020 5:29 PM