Weekly Report
Mar 23th -29nd
2021 Report # 34

### Norway House Cree Nation

Health Centre of Excellence



Project:

CD4 – Health Centre of Excellence

Aman Chana

Norway House, Manitoba



### Weekly Progress Report Mar 30, 2021, ID #285

### REPORT DETAILS

Description

Created by Aman Chana

1. WORK LOG			
Crew	# Workers	# Total hours	Work performed
JNR	30	1800	See below for discriptions
Totals	30	1800	

2. 0	2. CREW ONSITE			
2.1	2.1 The following crews were active in this report period			
	<b>/</b>	JNR		
		Mechanical		
	<u> </u>	Electrical		
		Masonry		
	<b>✓</b>	Structural Steel		
	=	Oakwood Roofing Mobilized to site General site review & setting up C-can & office trailer		

Norway House, Manitoba



### 3. ARCHITECTURAL

3.1 Ongoing Work

N/A

3.2 Completed Work

N/A

### 4. STRUCTURAL

4.1 Ongoing Work

Erection of roof structure Cross bracing in A2 Straightening and torqueing steel structure in A2 Placing Q-deck / Welding (A2) Erection of Glulam Structure (A3) Warping up exposed Glulam (A3)

4.2 Completed Work

Concrete

A1 Structural slab rebar install

**B1** Main Floor securing hoardings

**Building hoardings for grade beam (C2)** 

Concrete Pour (Structural Slab (A1) / Penthouse (B1) / Stair Slab (B1) - Ref attached drawing)

Preparing for concrete pour (A1-Structural Slab)

Poured concrete in Grade Beam (C2)

**Maintenance of Concrete Pump** 

### 5. MECHANICAL

5.1 Ongoing Work

Producing required shop drawing submittals -Ongoing

5.2 Completed Work

**Off Site for Turn Around** 

### 6. ELECTRICAL

### 19015D-NHCN-Health Centre

Norway House, Manitoba



6.1 Ongoing Work

Producing required shop drawing submittals -Ongoing

6.2 Completed Work

Working on temporary power hookup. Install hanger work packages in area A1, A2 Install work packages in area A1, A2 crawlspace

### 7. CIVIL

7.1 Ongoing Work

Operating Rock Truck / Excavator / Crawler Tractor Hauling / stockpiling clay for placing around the hospital

Surveyor Crawlspace topographic survey B1-1 as build survey of floor elevations. Drafting & data management

7.2 Completed Work

### 8. SAFETY AND COVID-19 SCREENING

8.1 Number of Covid Screening reports completed

JNR is continuing screening all visitors and staff daily who report to site. 180 Covid screening reports completed on site last week.

### 9. SITE VISIT SCHEDULE

9.1 Next scheduled site visit

Next scheduled visit to site is to be determined

### **NOTES**



### Concrete Pour Notes:

31.5 Cubic M. (Mix #3 - 12 Cubic M. / Mix #5 - 19.5 Cubic M.) of concrete was poured in (Structural Slab (A1) / Slab-on-deck Penthouse (B1) / Stair Slab (B1) - Slab pour drawing attached for ref.) 40 Cubic M. of concrete was poured in slab-on-deck (B1-1 - Slab pour drawing attached for ref.) 43 Cubic M. (Mix #2) of concrete was poured in Grade Beam (C2 - Pour drawing attached for ref.)

### PHOTOS (30)



A3- Wrapping up Glulam beams & column **Arshdeep Grewal** Mar 28, 2021 1:12 PM



A3- Wrapping up Glulam beams & column **Arshdeep Grewal** Mar 28, 2021 1:12 PM





B1 Penthouse - Fixing hoardings **Arshdeep Grewal** Mar 28, 2021 1:12 PM



B1- Surveyor checking elevation **Arshdeep Grewal** Mar 28, 2021 1:12 PM





Oakwood Roofing setting up office trailer **Arshdeep Grewal** Mar 28, 2021 1:12 PM




A2- Erection of Roof Structure Arshdeep Grewal Mar 28, 2021 1:12 PM





A2- Erection of roof structure **Arshdeep Grewal** Mar 27, 2021 1:15 PM



Compacting concrete poured in Grade Beam **Arshdeep Grewal** Mar 27, 2021 1:15 PM





C2- Pouring Grade Beam **Arshdeep Grewal** Mar 27, 2021 1:15 PM



C2- Concrete Pump used for pouring concrete

Arshdeep Grewal

Mar 27, 2021 1:15 PM





B1- Stair Slab Arshdeep Grewal Mar 27, 2021 1:15 PM



B1-1 - Slab-on-deck **Arshdeep Grewal** Mar 27, 2021 1:15 PM





B1-1 - Slab-on-deck **Arshdeep Grewal** Mar 27, 2021 1:15 PM



Aerial view of site

Wayne Dee

Mar 27, 2021 10:26 AM



Aerial view of site

Wayne Dee

Mar 27, 2021 10:26 AM



A3- Aerial view of Glulam Installed **Wayne Dee**Mar 27, 2021 10:26 AM





B1- Aerial view of hoardings around pouring areas **Wayne Dee** Mar 27, 2021 10:21 AM



Setting up concrete pump for pour **Wayne Dee** Mar 27, 2021 10:16 AM





A2- Structural steel
Wayne Dee
Mar 27, 2021 10:16 AM



Manitoba Hydro stringing cables from pole to C-Can **Arshdeep Grewal** Mar 26, 2021 8:24 AM





A1- Concrete pouring in Structural Slab **Arshdeep Grewal** Mar 26, 2021 8:24 AM



A1- Wescan Electrical installing hangers **Arshdeep Grewal** Mar 26, 2021 8:24 AM





A1- Sump pit cover Arshdeep Grewal Mar 26, 2021 8:24 AM



B1- Placing concrete over deck **Arshdeep Grewal** Mar 24, 2021 4:50 PM





A3- Preparing for Glulam installation **Arshdeep Grewal** Mar 24, 2021 4:50 PM



A1- Installing Q-deck Arshdeep Grewal Mar 24, 2021 4:50 PM





A2- Erection of roof structure Arshdeep Grewal Mar 24, 2021 4:50 PM



B1- Concrete Screed Arshdeep Grewal Mar 24, 2021 4:50 PM






B1- Smoothing concrete surfaces **Arshdeep Grewal** Mar 24, 2021 4:50 PM



A3- Erection of roof structure Arshdeep Grewal Mar 24, 2021 4:42 PM

## BACKFILL ACTIVITY




# CONCRETE SLAB ACTIVITY




SLAB IN-PROCESS


# FOOTING, PIER & GRADE BEAM ACTIVITY



# MASONRY ACTIVITY



## STRUCTURAL STEEL



## WEEPING TILE UPDATE

