Weekly Report
May 25th-June 1st
2021 Report # 43

Norway House Cree Nation

Health Centre of Excellence



Project:

CD4 – Health Centre of Excellence

Aman Chana

Norway House, Manitoba



Weekly Progress Report

Jun 1, 2021, ID #375

REPORT DETAILS

Description

Created by Aman Chana

1. WORK LOG			
Crew	# Workers	# Total hours	Work performed
Total Crew on Site	61	3660	See below for discriptions
Totals	61	3660	

2. CREW ONSITE

2.1 The following crews were active in this report period



0111



Electrical

Masonry

Structural Steel

Carlson
Roma Masonry
Oakwood Roofing

Norway House, Manitoba



3. ARCHITECTURAL

3.1 Ongoing Work

N/A

3.2 Completed Work

N/A

4. STRUCTURAL

4.1 Ongoing Work

STRUCTURAL STEEL

- -straightening structural steel (C1)
- -Installing cross bracing (C1)
- -Fastening Q-Deck (C1)
- -Installing Q-Deck (C2)
- -Installing stairs & landing areas (B1)
- -Installing exterior angle in A1
- 4.2 Completed Work

JNR CREW

- -Grouting where required
- -Installing brackets at C2
- -Hanging embeds at B2.
- -Clearing Q-Deck (A1)
- -Building curbs (C2 Ambulance Garage)
- -Installing tub recess frames and brackets B2
- -Preparing for concrete slab pour
- -General site clean up / Organizing material & moving material / Operated telehandler, fuel truck & Skid steer/dewatering

5. MECHANICAL

5.1 Ongoing Work

Producing required shop drawing submittals -Ongoing

- 5.2 Completed Work
 - -Install HYD pipe (B2)
 - -Install pipe for floor drains in loading dock (A1)
 - -Layout Lav carriers (B1)
 - -Installing sanitary work packages at area breaks in crawlspace
 - -Preparing for B1 main floor rough in

19015D-NHCN-Health Centre

Norway House, Manitoba



- -Working with mason for block wall openings and sleeves
- -Installing duct work in B1/C1 crawlspace and observing block wall openings
- -Preparing crawlspace sanitary for testing clean up of hangers and materials.

6. ELECTRICAL

6.1 Ongoing Work

Producing required shop drawing submittals -Ongoing

- 6.2 Completed Work
 - -Install conduit (A3 crawlspace)
 - -Received delivery and organized material on site
 - -Temp power work at Sigfusson camp
 - -Received delivery and organized material on site
 - -Rough-in electrical devices in area A1 block
 - -Wall rough-ins in area B1
 - -Rough-in electrical devices in area A1 block
 - -Pulling panel feeders cables in area B1, B2

7. CIVIL

7.1 Ongoing Work

CIVIL

- -Working on sweat lodge area
- -Clearing area for setting up camps spaces
- -Hauling sand

Surveyor

- -Laying out masonry wall
- -Concrete paver layout
- -Laying out sweat lodge
- -Drafting and data management
- -Exterior angle layout
- -Working on room co-ordination
- -Checking elevations
- 7.2 Completed Work

8. SAFETY AND COVID-19 SCREENING

19015D-NHCN-Health Centre

Norway House, Manitoba



8.1 Number of Covid Screening reports completed

JNR is continuing screening all visitors and staff daily who report to site. 610 Covid screening reports completed on site last week.

9. SITE VISIT SCHEDULE

9.1 Next scheduled site visit

Next Scheduled site visit is tentatively scheduled for June 10th.

NOTES

Oakwood Roofing:

On Turn around from site

Carlson

- -Interior framing (B1 & A3)
- -Exterior framing & sheathing (A2 GL between 6e/7e)
- -Started exterior walls in B2
- -Unloaded material and organized on site
- -Exterior framing & sheathing in penthouse
- -Laid out and organized top and bottom tracks in A2/A3
- -Top track cross bracing beam in fills and sheathing beam in fills B2
- -Building parapet A3 roof
- -Sheathing around and penthouse and cultural hall.
- -Unloaded material and organized on site

Roma Masonry

- -Getting organized on site
- -Remobilized to site on May 25th
- -Laying blocks along GL Ge working east from GL 4e to 14e.
- -Installing door frames in A1

Oakwood Roofing

- -Insulated, boarded and primed parapet walls A3
- -Started installing roof drains
- -Base sheet stripping on control joints locations

PHOTOS (35)





Stud framing in A2 **Anmol Kang**Jun 1, 2021 4:27 PM



Installing exterior angle **Anmol Kang** Jun 1, 2021 4:27 PM



Penthouse work in progress **Anmol Kang** Jun 1, 2021 4:27 PM



Exterior sheathng north side A3 **Anmol Kang**Jun 1, 2021 4:27 PM





Exterior sheathing in A1 **Anmol Kang**Jun 1, 2021 4:27 PM



Clearing space for camps **Anmol Kang** Jun 1, 2021 4:27 PM






B1 interior framing neat stairs **Anmol Kang** Jun 1, 2021 4:27 PM



Clearing sweat lodge area **Anmol Kang** May 31, 2021 4:41 PM






Layout for installing tracks **Anmol Kang** May 31, 2021 4:38 PM



Installing exterior studs in B2 **Anmol Kang** May 31, 2021 1:31 PM





Masonry wall along GL Ge **Anmol Kang** May 31, 2021 1:31 PM



Exterior stud framing in B2 Anmol Kang May 31, 2021 12:51 PM



Interior framing B1

Anmol Kang

May 31, 2021 12:48 PM



Masonry wall A1

Anmol Kang

May 31, 2021 12:44 PM





Masonry wall work in progress **Anmol Kang** May 31, 2021 12:43 PM



Working on tub depressions **Anmol Kang** May 28, 2021 4:18 PM






Laying masonry blocks in A1 along GL Ge **Anmol Kang** May 28, 2021 4:17 PM



Laying out bottom tracks in A2 **Anmol Kang** May 28, 2021 4:17 PM





Masonry wall work in progress **Anmol Kang** May 28, 2021 4:17 PM




Laying out bottom tracks in A2 **Anmol Kang** May 28, 2021 4:17 PM






Laying out sweat lodge Arshdeep Grewal May 27, 2021 11:24 AM



Stairs work in progress **Arshdeep Grewal** May 27, 2021 11:24 AM



Building curbs in ambulance garage **Arshdeep Grewal** May 27, 2021 11:24 AM



Interior framing in B1 **Arshdeep Grewal**May 27, 2021 11:24 AM





B1- Interior Framing Arshdeep Grewal May 26, 2021 10:16 AM



B1- Stair work progress **Arshdeep Grewal** May 26, 2021 10:16 AM



C2- Building formwork for curbs **Arshdeep Grewal** May 26, 2021 10:16 AM




B1- Interior stud framing Arshdeep Grewal May 26, 2021 10:16 AM





C1- Structural steel Arshdeep Grewal May 26, 2021 10:16 AM



B1- Stair work progress **Arshdeep Grewal** May 24, 2021 7:27 PM



B1- Interior stud wall **Arshdeep Grewal** May 24, 2021 7:27 PM



C1- Installing Q-Deck at roof level **Arshdeep Grewal** May 24, 2021 7:27 PM






B1- Interior stud wall Arshdeep Grewal May 24, 2021 7:27 PM




C1- Straightening structural steel **Arshdeep Grewal** May 24, 2021 7:27 PM




C1- Straightening structural steel **Arshdeep Grewal** May 24, 2021 7:27 PM



BACKFILL ACTIVITY




CONCRETE SLAB ACTIVITY




SLAB IN-PROCESS

EXTERIOR STEEL STUD FRAMING




NOTE: STUD FRAMING COMPLETE INDICATES COMPLETION OF STEEL STUD FRAMING SCOPE OF WORK AT A PARTICULAR AREA INCLUDING SHEATHING & PARAPET WHERE APPLICABLE.


FOOTING, PIER & GRADE BEAM ACTIVITY




INTERIOR STEEL STUD FRAMING




MASONRY ACTIVITY



ROOFING ACTIVITY



STRUCTURAL STEEL



WEEPING TILE UPDATE

