Weekly Report
June 30th-July 6th
2021

Report # 48

Norway House Cree Nation

Health Centre of Excellence



Project:

CD4 – Health Centre of Excellence

Aman Chana

JNR Construction

Norway House, Manitoba



Weekly Progress Report Jul 6, 2021, ID #420

REPORT DETAILS

Description

Created by Aman Chana

1. WORK LOG			
Crew	# Workers	# Total hours	Work performed
JNR AND SUB TRADES	51	3060	SEE BELOW
Totals	51	3060	

2. 0	2. CREW ONSITE				
2.1 The following crews were active in this report period					
	/	JNR			
	✓	Mechanical			
	<u> </u>	Electrical			
		Masonry			
	<u> </u>	Structural Steel			
	<u> </u>	Carlson			
	/	Oakwood			

Norway House, Manitoba



3. ARCHITECTURAL

3.1 Ongoing Work

N/A

3.2 Completed Work

N/A

4. STRUCTURAL

4.1 Ongoing Work

Wescan Structural

- -Straightening / welding / tightening joist (A1)
- -Installing cross bracing (A1)
- -Prep. for installing RTU supports (A1)
- -Preparing for Installing Q deck in A1
- -Installing Q deck in A1

JNR Site and Concrete Crew

- -General site clean up / Dewatering Checking pumps /Fueling / Operating concrete pump
- -Setting up table and prep. for loading dock area (A1)
- -Sorting and organizing lumber on site
- -Preparing ground for grade beam walls
- -Building grade beam formwork (A1)
- -Laying concrete pavers (B1 Crawlspace)
- -installing and grouting embeds
- -Working on de-contamination pad rebar in C2
- -Grouting and grinding GB
- -Priming and damp proofing GB
- 4.2 Completed Work

5. MECHANICAL

- 5.1 Ongoing Work
 - -Install backing for waterlines and vents in wall (B1)
 - -Install venting (B1)
 - -Install SAN pipe (B1 crawlspace)
 - -Install LAV carriers in walls (B1)
 - -Unit Heaters Arrived on Site
 - -Install SAN pipe (B2 crawlspace)
 - -Layout structural supports for RTU (A1)
 - -Prep. for Sanitary testing (A1 & A2)
 - -Install HYD hangers (B1)

19015D-NHCN-Health Centre

Norway House, Manitoba



- -Layout med gas systems (B1)
- -Prep for pipe install (B1)
- -Preparing for C1 slab pour
- -Installing chairs for in-floor loops
- -Installing Med Gas hangers B1
- -Preparing for B1 Hydronic rough in
- 5.2 Completed Work

6. ELECTRICAL

- 6.1 Ongoing Work
 - -Wire pull crawlspace lighting
 - -Working on sorting packages A3 rough-in
 - -Sleeves C1-C2
 - -Started rough in (A3)
 - -Installing conduits (A3)
 - -Installing crawlspace basket tray support
- 6.2 Completed Work

7. CIVIL

7.1 Ongoing Work

Surveyor

- -Room layout coordination
- -Layout at loading dock for grade beam (A1)
- -Checking elevations at front entrance (A3)
- -Drafting and data management
- -Laying out backing and blocking (B1)
- -Working on de-contamination tank slab layout
- -Laying out PA parking lot
- -Sweat lodge property line survey
- -Curtain wall survey

Civi

-Organizing and hauling rocks, making space for setting up new camps on east side of the site.

7.2 Completed Work



8. MASONRY

8.1 Ongoing Work

Not on site due to turn around

8.2 Completed Work

9. OAKWOOD ROOFING/SIDING

9.1 Ongoing Work

ROOFING

- -General site clean up and house keeping
- -Continue installing AVB (A3)
- -Building control joints (B1)
- -Installed flashing and AVB over penthouse (B1)
- -Torched vapor barrier over control joints (B1)
- -Moved materials onto roof
- -Installed flashing and AVB over C1 roof
- -Finished installing perimeter metal on C1
- -Installing fall protection around B2 roof

SIDING/CLADDING

-Not on site gone for turn around

9.2 Completed Work

10. CARLSON

- 10.1 Ongoing Work
 - -Exterior wall framing (B2)
 - -Laying out and installing tracks for interior walls (B1)
 - -Framing duct work opening (A2 & B1)
 - -Framing interior steel stud wall (A3)
 - -Prep. and organizing for future work
 - -Framing duct work opening (B1)
 - -Prep. for installing Drywall tops (B1)
 - -Framing interior steel stud wall (B1 & A3)
 - -Exterior sheathing (B2)
 - -Installing plywood around window openings (B2)
 - -Installing bottom tracks in (B1-3)
- 10.2 Completed Work



11. SAFETY AND COVID-19 SCREENING

11.1 Number of Covid Screening reports completed

JNR is continuing screening all visitors and staff daily who report to site. 306 Covid screening reports completed on site last week.

12. SITE VISIT SCHEDULE

12.1 Next scheduled site visit

is scheduled for July 8th for a site review

PHOTOS (26)



Ductwork in B1 **Anmol Kang**Jul 6, 2021 5:26 PM



Installing bottom track **Anmol Kang** Jul 6, 2021 5:26 PM





Working on conduit runs in A3 **Anmol Kang** Jul 6, 2021 5:24 PM



Installing sprinkler lines in crawlspace **Anmol Kang** Jul 6, 2021 5:23 PM




B2 exterior sheathing **Anmol Kang** Jul 6, 2021 5:24 PM



Creating space for new camps **Anmol Kang** Jul 6, 2021 5:22 PM





B1 Corridor Anmol Kang Jul 6, 2021 5:22 PM




B2 exterior sheathing work in progress **Anmol Kang** Jul 6, 2021 5:21 PM






Preparing deck C1 for pour **Anmol Kang**



Cleaning deck for pour **Anmol Kang** Jul 6, 2021 5:15 PM



B1-3 interior framing **Anmol Kang** Jul 6, 2021 5:17 PM




Laying bottom tracks in B1-3 **Anmol Kang** Jul 6, 2021 5:13 PM





Interior framing A3 **Anmol Kang**Jul 5, 2021 4:30 PM



Intalling conduit runs **Anmol Kang** Jul 5, 2021 4:29 PM



B1-3 interior stud framing Anmol Kang Jul 5, 2021 4:28 PM



A1 steel structure over masonry **Anmol Kang** Jul 4, 2021 3:56 PM





A1 steel structure over Masonry A1 **Anmol Kang** Jul 4, 2021 3:55 PM



Dry wall installed in B1 **Anmol Kang** Jul 4, 2021 3:55 PM



Formwork for exterior GB Loading dock **Anmol Kang** Jul 4, 2021 3:55 PM



A3- Framing exterior wall around front entrance **Arshdeep Grewal** Jul 2, 2021 2:55 PM





B1- Installed hangers Arshdeep Grewal Jul 2, 2021 2:55 PM




A1- Installing RTU supports **Arshdeep Grewal** Jul 2, 2021 2:55 PM





A1- Cross bracing between joist Arshdeep Grewal Jul 2, 2021 2:55 PM



B2- Installing exterior wall sheathing **Arshdeep Grewal** Jun 29, 2021 3:52 PM







C1- Block out for recessed track **Arshdeep Grewal** Jun 29, 2021 3:52 PM




C2- Erection of roof structure **Arshdeep Grewal** Jun 29, 2021 3:52 PM



BACKFILL ACTIVITY




CONCRETE SLAB ACTIVITY




SLAB IN-PROCESS

EXTERIOR STEEL STUD FRAMING




NOTE: STUD FRAMING COMPLETE INDICATES COMPLETION OF STEEL STUD FRAMING SCOPE OF WORK AT A PARTICULAR AREA INCLUDING SHEATHING & PARAPET WHERE APPLICABLE.


FOOTING, PIER & GRADE BEAM ACTIVITY




INTERIOR STEEL STUD FRAMING




MASONRY ACTIVITY




ROOFING ACTIVITY




STRUCTURAL STEEL



EXTERIOR WALL



EXTERIOR WALL



WEEPING TILE UPDATE

