Weekly Report #62

Dec 1st-7th 2021

Norway House Cree Nation

Health Centre of Excellence



Project:

CD4 – Health Centre of Excellence

Aman Chana

Norway House, Manitoba



Weekly Progress Report

Dec 7, 2021, ID #600

REPORT DETAILS

Description

Created by Aman Chana

Status Draft

Last update Dec 14, 2021 5:03 PM

Last updated by Aman Chana

1. WORK LOG

Crew	# Workers	# Total hours	Work performed
JNR and Subtrades	110	6505	See below
Totals	110	6505	

2. CREW ONSITE

2.1 The following crews were active in this report period



Mechanical

Electrical

Masonry

Structural Steel

Carlson

Oakwood

19015D-NHCN-Health Centre

Norway House, Manitoba





Wisl (Firestopping)

-Working on firestopping / smoke seal (B2 - South Corridor)

Valour Decorating

- -Painting exposed ceiling in electrical room (A1)
- -Prep. for sealing block walls (A1- Electrical Room)

3. ARCHITECTURAL

- 3.1 Ongoing Work
 - -Working on backing in B1 and A2
 - -Working on RTU curbs B2 roof
 - -Working on maintain heat inside building
 - -Working on insulating GB C2 North and ambulance bay
 - -Working on warming up shack between C-Cans
 - -Working on hoarding propane pad

General site clean up / Hauling water for washroom / Fueling / Checking pumps, fans & de-humidifiers / Removing garbage / Moving material on site / Operating zoom boom, fuel truck/ Snow removal

3.2 Completed Work

N/A

4. STRUCTURAL

4.1 Ongoing Work

JNR Concrete Crew

- -Pouring and finishing housekeeping pads
- -Working on rebar at propane pad
- 4.2 Completed Work

5. MECHANICAL

5.1 Ongoing Work

-B2 South hallway hanger install

19015D-NHCN-Health Centre

Norway House, Manitoba



- -B1 medical gas install
- -B2 In-wall rough in south
- -B2 South hallway high level hydronic install
- -B2 In-wall rough in south
- -B2 venting install
- -Review RTU curbs for upcoming craning
- -Install controls conduit in area B1
- -Install conduits from main floor to crawlspace
- -Terminate VAV and RHC in B1
- -Insulation work in B1
- -Insulate water mains B1 corridor
- -Insulation work in A2
- 5.2 Completed Work

6. ELECTRICAL

- 6.1 Ongoing Work
 - -Door security B2
 - -B1 room review
 - -Rack install building roof
 - -Cable management A1
 - -BI conduit packages
 - -A2 pipe packages installed
 - -Install conduit work packages in area A1, A2 and B1
 - -Pull feeder cables on roof.
 - -Trench from CSTE to MB Hydro transformer
 - -Room review and correct deficiencies for area B1
 - -Install conduit work packages in area B1 corridor 1:31
- 6.2 Completed Work

7. CIVIL

7.1 Ongoing Work

Civil

- -Cleared snow
- -Working on tank farm.

JNR Surveyor

- -Backing layout & monitoring B1/A2
- -Drafting & data management
- 7.2 Completed Work



8. MASONRY

8.1 Ongoing Work

- -Installing bricks clips C1 East
- -Rubbing and patching walls
- -Working on internal block wall A1
- -Rubbing and patching walls
- -Removing scaffolding
- -Setting up scaffolding B2 South
- -Moving material/ Hoarding over scaffolding
- -Installing brick ties (C2)
- 8.2 Completed Work

9. OAKWOOD ROOFING/SIDING

9.1 Ongoing Work

SIDING

- -Installing wall insulation C2 North
- -Working on panels and rims around scuppers A1,A3 and B1
- -Preparing for thru wall flashing over veneer
- -Installing thru wall flashing over veneer B2 North
- -Sealing around brick ties C2
- -Installing TG AVB in C2
- -Installed curb cap flashing for roofers
- -General house keeping

ROOFING

- -Working on control joint C1 roof
- -Sealing RTU curb C2
- -Installed flashing around ambulance bay roof
- -Sealed C2 South projection
- -Sealing RTU curb A1
- -Insulating C1 roof
- -Installing recovery board on control joint (C1)
- -Torching base stripping on control joint (C1)
- 9.2 Completed Work

10. CARLSON

10.1 Ongoing Work

19015D-NHCN-Health Centre

Norway House, Manitoba



- -Framing interior steel stud (B2)
- -Installing drywall tops (B2)
- -Framing interior steel stud (A1) over block wall
- -Installing dry wall over block wall
- -Framing double wall for headwalls (B1)
- -Laying out interior walls (A1)
- -Installing bottom & top tracks (A1)
- -Prep. for framing around cultural hall (A3)
- 10.2 Completed Work

11. SAFETY AND COVID-19 SCREENING

11.1 Number of Covid Screening reports completed

JNR is continuing screening all visitors and staff daily who report to site. 676 Covid screening reports completed on site from this time period.

12. SITE VISIT SCHEDULE

12.1 Next scheduled site visit

JNR on site Dec 13th L.M and consultants scheduled to be on site Dec 15th

PHOTOS (31)





Rough in work on going in B1 **Anmol Kang** Dec 6, 2021 5:59 PM



Dry wall tops installed in A1 **Anmol Kang** Dec 6, 2021 5:58 PM




Backing done for stairs in B1 **Anmol Kang** Dec 6, 2021 5:58 PM



Insulation installed C2 Anmol Kang Dec 6, 2021 5:50 PM





Framing over block wall **Arshdeep Grewal** Dec 6, 2021 5:30 PM




Tying rebar for propane pad **Arshdeep Grewal** Dec 6, 2021 5:26 PM





A2- East finger corridor progress **Arshdeep Grewal** Dec 6, 2021 5:26 PM



A1 Electrical Room- Mudding & tapping drywall **Arshdeep Grewal** Dec 6, 2021 5:26 PM





B2- Installing drywall tops **Arshdeep Grewal** Dec 6, 2021 5:26 PM



B1- Installing conduits & junction boxes **Arshdeep Grewal** Dec 6, 2021 5:26 PM





Heating ground for trenching Anmol Kang Dec 5, 2021 3:28 PM



Backing in A2


Anmol Kang

Dec 5, 2021 3:22 PM





B2 drywall tops installation on going **Anmol Kang** Dec 5, 2021 3:18 PM



High elevation pipe installation on going B2 **Anmol Kang** Dec 4, 2021 2:44 PM





Working on backing in A2 **Anmol Kang** Dec 4, 2021 2:37 PM



B2 Hoarded Anmol Kang Dec 4, 2021 2:33 PM



Bent flasing installed C1 **Anmol Kang** Dec 4, 2021 2:36 PM



Insulation installed C2 North **Anmol Kang**Dec 4, 2021 2:30 PM





Working on wall insulation C2 **Anmol Kang** Dec 3, 2021 3:20 PM



Anmol Kang
Dec 3, 2021 3:13 PM



Flasing over masonry **Anmol Kang** Dec 3, 2021 3:15 PM



Backing work in A2 **Anmol Kang**Dec 3, 2021 3:13 PM





Hoarding setup for propane pad **Anmol Kang** Dec 3, 2021 3:12 PM




Rougn in work on going A2 **Anmol Kang**Dec 2, 2021 5:16 PM





Rough in work in A2 **Anmol Kang**Dec 2, 2021 5:16 PM



Drywall over black wall A1 **Anmol Kang**Dec 2, 2021 5:15 PM





Working on scuppers **Anmol Kang** Dec 2, 2021 5:15 PM



House keeping pads poured **Anmol Kang** Dec 2, 2021 5:15 PM






Working on RTU curb C1 roof **Anmol Kang** Dec 2, 2021 5:14 PM



Pads poured in mech room A1


Anmol Kang

Dec 2, 2021 5:12 PM




B2 interior framing **Anmol Kang** Dec 2, 2021 5:12 PM

DRYWALL TOP PROGRESS




AREA **EXTERIOR WALL** % COMPLETION EXTERIOR STEEL STUD FRAMING **A1** 100 A2 100 **A3** 100 **B**1 100 COMPLETE COMPLETE STUD FRAMING STUD FRAMING T.O. PARAPET ELEV. 109 700 U/S STEEL DECK ELEV. 109 200 B2 COMPLETE STUD FRAMING 100 99 (+2) 95 COMPLETE STUD FRAMING COMPLETE STUD FRAMING C9W STUD FRAMING T.O. PARAPET ELEV. 105 600 U/S STEEL DECK ELEV. 104 970 45w CAP SHEET WALKWAYS LAYOUTS REVISED TO SUIT EQUIPMENT ACCESS AND GENERAL NOTES. COMPLETE STUD FRAMING Te ACTIVE STUD FRAMING COMPLETE STUD FRAMING COMPLETE STUD FRAMING ACTIVE STUD FRAMING Work Complete Work In-Progress




NORWAY HOUSE HEALTH CENTRE OF EXCELLENCE WEEKLY UPDATE DECEMBER 05TH 2021

INTERIOR STEEL STUD FRAMING


AREA	INTERIOR WALL % COMPLETION
A1	85 (+5)
A2	97
A3	87
B1	99
B2	88 (+3)
C1	0
C2	0



MASONRY ACTIVITY



NORWAY HOUSE HEALTH CENTRE OF EXCELLENCE WEEKLY UPDATE DECEMBER 05TH 2021



EXTERIOR WALL & GRADE BEAM LAYERS



EXTERIOR WALL & GRADE BEAM LAYERS

